## Why Planar Magnetics are Ideal for Harsh Environments

Jim Marinos
Payton America Inc.
Jim@paytongroup.com

Reliability is a major factor on a military or a space environment. Reliability is driven by a few factors, such as simplicity of the design, number of components, proven materials and testing.

Producibility is another critical point. From the 1<sup>st</sup> sample and 10+ years later the data stays the same.

Solid mechanical geometry provides a solid and demonstrated performance to high vibration and shock.